

And converting from Ra to Rz and vice versa has no established ratio, either. Values range from 4-to-1, up to 20-to-1 and can be further influenced by the part's shape.

So, with all these variations, not only in the part, but in the measurement criterion, what's a part maker to do? Establish both your criteria and the customers up front, know what their measuring method and equipment will be and agree on any conversion ratios well beforehand. Last, communicate throughout the production process so that at the end of the project, they're happy, and you're paid.

For more info, read up on this topic here: short.productionmachining.com/RaRzDiff

To create even more confusion, the Rz calculation has changed over the years, resulting in three different calculations.

short.productionmachining.com/RaToRz

Rz is "mean roughness step," and it is a more

common measurement parameter in Europe. Again from *Modern Machine Shop*, "Rz is calculated

ence on the final value."

by measuring the vertical distance from the high-

est peak to the lowest valley within five sampling

lengths, then averaging these distances. Rz averages

only the five highest peaks and the five deepest val-

leys-therefore extremes have a much greater influ-

All Craftsman's Cribsheets are available for viewing and download at short.productionmachining.com/cribsheets.